

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	"63121337"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/06 14:50
S1	47	kalender.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:16
S2	79	stober.as.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:19
S3	1080	361/23.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:19
S4	767	361/31.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:36
S5	7	361/31.ccls. and convertor not A/D	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:38
S6	65	361/31.ccls. and converter not A/D	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:38
S7	43	361/31.ccls. and converter not A/D and switch\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:45

S8	2	switched\$1off\$1state	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:46
S9	4905976	switch state	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:47
S10	11352	switch adj state	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:47
S12	642	switch adj state near3 detect\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:48
S13	671	switch adj state near3 (detect\$3 measur\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:49
S14	905	switch adj state near3 (detect\$3 measur\$3 sens\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:49
S15	13	switch adj state near3 (detect\$3 measur\$3 sens\$3) same converter	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:52
S16	1	switch adj state near3 (detect\$3 measur\$3 sens\$3) same converter same motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:53

S17	89	(switch near3 position) near3 (detect\$3 measur\$3 sens\$3) same converter same motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/01 16:55
S18	6	("3348108").URPN.	USPAT	OR	OFF	2005/09/01 17:12
S19	3807	(plurality near2 motors)	USPAT	OR	OFF	2005/09/01 17:13
S20	1645	(plurality near2 motors) and switch	USPAT	OR	OFF	2005/09/01 17:13
S21	363	(plurality near2 motors) and switch and converter	USPAT	OR	OFF	2005/09/01 17:13
S22	259	(plurality near2 motors) and switches and converter	USPAT	OR	OFF	2005/09/01 17:13
S23	259	(plurality near2 motors) and switches and converter	USPAT	OR	OFF	2005/09/01 17:14
S24	189	(plurality near2 motors) and switches and converter not A/D	USPAT	OR	OFF	2005/09/02 08:31
S25	0	"6252751.pn.n"	USPAT	OR	OFF	2005/09/02 08:31
S26	1	"6252751".pn.	USPAT	OR	OFF	2005/09/02 08:31
S27	13	("3790871" "4106013" "4289997" "4511947" "4669037" "4812729" "4829217" "5040088" "5113684" "5136222" "5177657" "5589743").PN. OR ("6252751").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 08:58
S28	564	318/102.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 09:23
S29	9	318/102.ccls. and current near2 sens\$3	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 08:59
S30	5	("3317802").URPN.	USPAT	OR	OFF	2005/09/02 09:08
S31	9	318/102.ccls. and converter	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 09:26
S32	9	318/101.ccls. and converter	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 09:58
S33	10	("3710214" "4267704" "5041775" "5272427" "5492273" "5572104" "5594312" "6002218" "6021955" "6116513").PN. OR ("6680589"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 09:46
S34	0	318/101.ccls. and (reley near3 monitor\$1)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 09:59

S35	2	318/101.ccls. and (relay near3 monitor\$1)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 10:00
S36	0	318/101.ccls. and (contact near3 monitor\$1)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 10:00
S37	1	318/101.ccls. and (contact near3 sens\$3)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 10:28
S38	373	current same relay same sensing same monitor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 10:14
S39	31	(relay adj monitor) and motor and switch and control	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 10:14
S40	61	318/791.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 10:30
S41	333	318/800.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 12:02
S42	23	servo adj converter	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 12:11
S43	528	318/625.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:14
S44	1053	318/625.ccls. (mutual adj lock\$3)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:15
S45	0	318/625.ccls. and (mutual adj lock\$3)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:15
S46	4	"318".clas. and (mutual adj lock\$3)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:17
S47	11	"318".clas. and (error fault) same relay same stuck	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:23
S48	92	(error fault) same relay same stuck	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:23
S49	2	(error fault) same relay same stuck same converter	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:23
S50	8	(error fault) same relay same (stuck fused welded) same converter	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:27

S51	9	(error fault) same relay same (stuck fused welded) same converter	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 13:29
S52	19	(error fault) same (relay contact\$1) same (stuck fused welded) same converter	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 13:40
S53	2	"6680589".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 13:40
S54	10	("3710214" "4267704" "5041775" "5272427" "5492273" "5572104" "5594312" "6002218" "6021955" "6116513").PN. OR ("6680589").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 13:53
S55	683	361/23.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:07
S56	3	361/23.ccls. and (relay same contact same converter)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:08
S57	0	"361.clas" and (relay same contact same converter)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:08
S58	167	"361".clas. and (relay same contact same converter)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:09
S59	68	"361".clas. and (relay same contact same converter same (monitor\$3 sens\$3 detect\$3))	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:12
S60	37	"361".clas. and ((relay same switch) same contact same converter same (monitor\$3 sens\$3 detect\$3))	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:14
S61	300	relay adj protection	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:14
S62	227	shorted adj contact	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:15
S63	354	faulty adj contact	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:15

S64	1226426	faulty adj contact motor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:16
S65	88	faulty adj contact and motor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:16
S66	88	(faulty adj contact) and motor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:18
S67	3	(faulty adj relay adj contact)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:19
S68	372	(fused adj contact)	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:19
S69	1226483	(fused adj contact) motor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:20
S70	49	(fused adj contact) and motor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:32
S71	40	soft adj weld	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 15:59
S72	14	soft adj weld same contact	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:00
S73	1	soft adj weld same relay	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:00
S74	40	soft adj weld	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:01
S75	0	("2002/0109570").URPN.	USPAT	OR	OFF	2005/09/02 16:01
S76	1	DIG42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:27
S77	0	DIG42.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:27

S78	0	Dig1.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:33
S79	0	(361/DIG.42).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:38
S80	0	(335/DIG.42).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:38
S81	0	(335/DIG.42)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:38
S82	0	(335/DIG42)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:38
S83	0	(335/DIG42).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:39
S84	0	(200/DIG42).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:39
S85	0	(200/DIG42)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:40

S86	694	(200/1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:40
S87	4	(200/dig)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:40
S88	5	(200/dig S76)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:41
S89	99	(200/dig.42)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:41
S90	96	(200/dig.42).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/02 16:41
S91	8	("4105882").PN. OR ("4645886"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:43
S92	14	("3364419" "4645886" "4870364" "5097830" "5153522" "5182517" "5227729" "5243291" "5285779" "5398025" "5455733").PN. OR ("5748427"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:55
S93	221	324/415.ccls.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/06 09:33
S94	246914	324/415.ccls. relay	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:57
S95	79	324/415.ccls. and relay	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/02 16:57
S96	24	324/415.ccls. and relay and motor	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/06 10:34

S97	1	"5243291".pn.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/06 09:33
S98	17	324/415.ccls. and converter	US-PGPUB; USPAT; USOCR	OR	OFF	2005/09/06 10:34
S99	3	deposition same contacts same converter same motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/06 10:49
S10 0	32	deposition same contacts same converter	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/06 12:25
S10 1	2	"6680589".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/09/06 14:49